



5/9/2009

**RELIABILITY MONITOR REPORT
FOR**

Dallas 0.35 μ m "D" Silicon Gate CMOS

MAXIM Integrated Products

120 San Gabriel Dr.
Sunnyvale, CA 94086

**This Report was prepared by
Maxim Reliability Engineering**

Summary:

The data in the tables that follow was generated as the result of an on-going Process Reliability Monitor. The specific products in this process monitor are:

DS1080CL

The calculated failure rate for devices using this process is:

FAILURE RATE: **MTTF (YRS): 5288** **FITS: 21.6**

The parameters used to calculate this failure rate are as follows:

Cf: 60% **Ea: 0.7** **Tu: 25 °C**

The reliability data follows and in this section is the detailed reliability data by stress. The reliability data section includes the latest data available. This report covers data between 4/1/2008 and 3/31/2009 .

Process Information:

Process Description: Dallas 0.35µm "D" Silicon Gate CMOS

OPERATING LIFE

DESCRIPTION	DATE CODE	TEST VEHICLE	CONDITION	READPOINT	QUANTITY	FAILS	LOT NO.
HIGH TEMP OP LIFE	0811	DS1080CL	125C, 3.6 VOLTS	1000 HRS	45	0	QD823625BB-NPI
					Total:	0	

FAILURE RATE: **MTTF (YRS): 5288** **FITS: 21.6**